

General Environmental Incident Summary

Incident: 3830 **Date/Time Notice:** 7/22/2015 1650 **DEM Incident No:**
Responsible Party: Great Northern Gathering and Marketing LLC
Date Incident: 7/22/2015 **Time Incident:** 1340 **Duration:** 30 minutes
County: McKenzie **Twp:** 149 **Rng:** 98 **Sec:** 30 **Qtr:**
Lat: 47.69236 **Long:** -103.27660 **Method:** Interpolation from map
Location Description: Great Northern Gathering and Marketing LLC. Watford City Receipt Point,
1918 Spring Creek Road Watford City ND, 58854
Submitted By: Rick Kerzman **Affiliation:** HSE Manager
Address: 2101 46th Ave SE
Suite 2
City: Mandan **State:** ND **Zip:** 58544

Received By:

Contact Person: Rick Kerzman
1201 Louisiana Street
Suite 3400
Houston, TX 77002

Distance Nearest Occupied Building: 1 Miles **Release Contained:** Yes

Type of Incident: Pump Leak

Description of Released Contaminant: Bakken Crude Oil

Volume Spilled: 2.00 barrels **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

unknown at this time

Risk Evaluation:

No immediate risk to personnel

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

impacted surface soil on site, immediately cleaned up

Action Taken or Planned:

isolated equipment, contained spill using oil only adsorbent socks, used skid steer to scrape affected area and loaded dirt in trailer and some on black plastic, to be removed with subsequent trips.

Wastes Disposal Location: At an approved site, most probably Nuverra landfill, Arnegaard

Agencies Involved:

Updates

Date: 7/23/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Volume:

Notes:

Release, due to a pump leak, at a non-E&P exempt location. Follow-up is required.

Date: 7/29/2015 **Status:** Inspection

Author: Crowdus, Kory

Updated Volume:

Notes:

On location 7/29/15, at 9:10am. Met with company personnel who took me to area of release. Soil has been excavated and is being stockpiled on location awaiting disposal. There does not appear to be any remaining impact at this time. Samples were taken by company. No further follow-up needed.